


NOTES:

1. NO HORIZONTAL ALIGNMENT CHANGE CAN BE MADE WITHIN THIS MANHOLE TYPE. USE ON GRADES OF 10% OR GREATER.
2. EACH JOINT OF PIPE BETWEEN HIGH VELOCITY MANHOLE & MANHOLE UPGRADE SHALL HAVE A THRUST COLLAR (SEE STANDARD DETAIL 06000.14).



EFFECTIVE: 12/10/09

STANDARD HIGH VELOCITY MANHOLE INVERT

DETAIL No.

07000.09

SHEET 1 OF 1